

Here are the parts descriptions on the back of the CD-2000:

1. **DEBUG:** USB connector for Main board, LCD board – for debugging
2. **C/U:** USB connector for CIS board
3. **P/P:** Connector for Thermal Printer
4. **D/P:** Connector for external display
5. **USB:** Connector for S/W upgrade - Main, LCD, CIS

